



Case Study: Confetti Bridesmaid

Eliminating mould at the source

Overview

- High-end bridesmaid boutique in Wandsworth, London
- Housed in an old building prone to damp
- Basement changing suite, where brides and bridesmaids try on dresses, is most exposed to that damp

The Challenge

- Persistent mould in the storage area, putting stock at risk of damage
- Mould also present in the changing suite, affecting conditions for brides and bridesmaids trying on dresses

The Solution

- MOULDZAP applied directly to the affected mould areas#
- Also sprayed across other areas prone to mould, to stop it taking hold before it starts

The Benefits

- Mould eliminated at the source, not just masked
- No recurrence in the year since treatment
- Stock protected from mould damage in storage
- Changing suite restored to a space brides and bridesmaids can trust
- Non-toxic treatment, safe to use around dresses and customers

Industry

Retail

Location

London



Before:

Dark, visible mould stains



1 year after:

Mould has not returned



[Contact Us](#)