



## Case Study: Office washroom

# Fast, safe, & reliable drain clearing

### Overview

- Busy office facility
- Repeated sink blockages in staff washrooms
- Odour complaints from employees

### The Challenge

- Multiple sinks had become blocked due to a build-up of soap residues, organic debris, limescale and mineral deposits.
- Traditional drain openers were too aggressive and posed a health and safety concern.

### The Solution

- DRAINZAP, an advanced oxidising drain treatment, was applied directly to the blocked sinks.
- Normal drainage was restored without mechanical tools or corrosive chemicals.
- The process was completed efficiently with minimal disruption to operations.

### The Benefits


- Rapid removal of blockages.
- Odour-free washrooms and improved user experience.
- Environmentally responsible solution using controlled oxidation technology
- Reduced manual intervention.
- No need for harsh chemicals or disruptive maintenance.

### Industry

Office space

### Location

North West, England



#### Before:

Blocked sinks disrupting daily use.



#### During:

DRAINZAP activating, foaming up to cover all pipe surfaces



#### After:

Free flowing drains following treatment with DRAINZAP.



[Contact Us](#)